

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated: 25-06-26

It is certified that the existing building Darshan Academy Sundargarh (name of the building or premises) at Pradhan Pat, Mahulpali, Sundargarh

Odisha 770002 (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Ground					

The building is owned/occupied by Darshan Education Foundation (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of (Name of Department/ Govt.) on (date of inspection) in the presence of Sri. Rupesh Patel (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 25.6.26 for a period of One years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on 25.6.26 at Sundargarh by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : [Signature]

Name : Superintending Engineer

Designation : Sundargarh (R&B) Division

Name & Address of Department/ Office: _____

[Signature]
25.6.26
Assistant Engineer
Lephpara (R&B) Section

[Signature]
25/06/26
Assistant Executive Engineer
Hemgir, R&B Sub-Division
Sundargarh

[Signature]
Principal
Darshan Academy
Sundargarh

[Signature]
Manager
Darshan Academy
Sundargarh